

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/13/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
08:00	<ul style="list-style-type: none"> Internal Command and General Staff meeting 		
09:00	<ul style="list-style-type: none"> Boat safety meeting at C0.4 boat launch. Launch. MP5.20 LDB sheen observed after a large carp swam away. Ceresco Dam control point boom observed sheen and debris collecting along the boom. MP5.25 RDB sheen and tar globs observed. MP4.75 LDB area where sheen and tar globs were observed. MP4.75 LDB sheen and tar globs observed. MP10.25 RDB observed an RI crew. MP15.75 RDB North Mill Pond area where sheen and tar globs were observed. MP15.75 RDB observed sheen and tar globs. MP15.5 LDB sheen and tar globs observed. MP15.25 LDB sheen and tar globs observed. MP15.0 LDB side channel sheen and tar globs observed. MP14.5 LDB sheen and tar globs observed. Morrow Lake north cove area where sheen and tar globs were observed. Morrow Lake north cove sheen and tar globs observed. Morrow Lake Delta Gate F observed sheen and tar globs collecting along the boom. Morrow Lake Delta Gate E observed sheen and tar globs collecting along the boom. Morrow Lake Delta Gate C observed a Bathymetry team. Morrow Lake Delta Gate C observed a crew inspecting the curtain. 		
16:00	Returned to Boat Launch C0.4. Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			